





## <u>WEST ELEVATION</u>

Looking East

\* - The existing rail post shall be removed during the repairs and the anchor devices shall be reused. The existing steel rail tubing shall remain in place during the work. Cost included with Structural Repair of Concrete.

## BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Deck Drain Extensions	Each	12
Structural Repair of Concrete (Depth Equal to or less than 5 inches)	Sq. Ft.	20

## NOTE:

Repairs shall include but not be limited to the areas shown.
The actual areas to be determined by engineer at the time of construction.

## LEGEND:

Structural Concrete Repairs
(Depth equal or less than 5 inches)

SUPERSTRUCTURE REPAIRS II
U.S. 52 OVER N. BR. JACKSON CREEK
STA. 524+51.00
S.N. 099-0129

SHEET NO. 55 | F.A.P. | SECTION | COUNTY | SHEETS | NO. 56 |

S6 SHEETS | CONTRACT | NO. 60D84 |

FED. ROAD DIST. NO. | ILLINOIS | FED. AID | PROJECT

DESIGNED E. Mroczek

CHECKED B. Sauter

DRAWN R. Danley

CHECKED E. Mroczek

